



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

EMNRD

AUG 10 2018

DISTRICT III

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-9-18 Operator DJR Operating LLC API #30-0 45-33803
Property Name Bist. Gallup Well No. 6 Location: Unit F Section 18 Township 25 Range 12
Well Status(Shut-In or Producing) Initial PSI: Tubing 85 Intermediate N/A Casing 0 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 4 INTERMEDIATE N/A

REMARKS: down to nothing in 1 second - gas sample
taken on tubing - BH.
is there a packer in hole.

By Jacob Harter
Jacob Harter
(Position)

Witness Monica Kuchling

E-mail address jharter@cottonwoodconsulting.com