

**BRADENHEAD TEST REPORT**

(Submit 1 copies to above address)

Date of Test July 17, 2018 Operator MANANA API #30-0 45-33818  
 Property Name CROOKED SEAMS Well No. 2 Location: Unit A Section 14 Township 30N Range 12W  
 Pressure (Shut-In or Producing) Shut in Tubing 0 Intermediate      Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE		Steady Flow	Surges	Down to Nothing	Nothing	Gas	Gas & Water	Water	BRADENHEAD	INTERMEDIATE
	BH	INT	CSG	INT	CSG								FLOWED	FLOWED
5 minutes	0		40											
10 minutes	0		40											
15 minutes	0		40											
20 minutes	0		40						X					
25 minutes	0		40											
30 minutes	0		40											

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN \_\_\_\_\_ BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Bradenhead had absolutely no pressure or gas fumes during entire test. This is a rod pumped well.

By Theo Hampton Witness \_\_\_\_\_  
Lease operator  
 (Position)

NMOCG  
 AUG 06 2018  
 DISTRICT III