



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 30 AUG 2018 Operator HILLTOP API #30-0 45-05726

Property Name BUD-05-PAH Well No. 1 Location: Unit 19 Township 26 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 3 Intermediate N/A Casing 4 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	4		
10 min	0		4		
15 min	0		4		
20 min	0		4		
25 min	0		4		
30 min	0		4		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 6

INTERMEDIATE N/A

REMARKS:

THE INTERMEDIATE IS CEMENTED SCHEMATIC IN FILE

OPENED THE BRADENHEAD AND IT MADE 4 GALLONS OF WATER IN 10 MINUTES REQUESTED A WATER ANALYSIS

By CHS MM

Witness [Signature]

(Position)

E-mail address _____

NMOCD

AUG 31 2018

DISTRICT III