



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-22-18 Operator 4/1 Corp API #30-0 45-31619
Property Name Furnington Lake Well No. 2 Location: Unit 21 Section 21 Township 30 Range 12
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 0 Intermediate 1/1 Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>5</u>		
10 min	<u>0</u>		<u>5</u>		
15 min	<u>0</u>		<u>5</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

NMOC
AUG 23 2018
DISTRICT III

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/1

REMARKS:

Nothing when opened. (Nothing when
opened after 5 min shut in

By

Kalan Kibbe

Witness

Monica Cuthbert

(Position)

E-mail address _____