



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC D

JUN 14, 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-13-18 Operator McG Duling Co. Inc. API #30-0 45-22920
Property Name Fludie Well No. 68 Location: Unit M Section 14 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>10</u>		
10 min	<u>0</u>		<u>10</u>		
15 min	<u>0</u>		<u>10</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Stuffing box leak - Duff when opened
Nothing when opened after 5 min shut-in

By [Signature]

Witness Monica Kuehling

(Position):

E-mail address

NMOC D

AUG 27 2018

DISTRICT III