



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 8-21-18 Operator SG Interests I, Ltd. API #30-045-24159

Property Name SE Cha Cha Unit Well No. 36 Location: Unit 2 Section 8 Township 28N Range 13W

Well Status(Shut-In or Producing) Initial PSI: Tubing 90 Intermediate N/A Casing 18 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>18</u>		
10 min	<u>0</u>		<u>18</u>		
15 min	<u>0</u>		<u>18</u>		
20 min	<u>0</u>		<u>18</u>		
25 min	<u>0</u>		<u>18</u>		
30 min	<u>0</u>		<u>18</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Less than 1 psi and blew down in 3 seconds.

By Brian McKinney  
Superintendent NIKK  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_

NMOCD  
AUG 27 2018  
DISTRICT III