

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director
Oil Conservation Division



September 12, 2018

Benson-Montin-Greer Drilling Corp

Attn: Matt Dimond

4900 College Blvd

Farmington, NM 87402-7402

Re: 2018 Bradenhead Test

Well: La Plata Mancos Unit #7, UL M Sec 29 Twn 32N Rge 13W, API # 30-045-21519

Dear Mr. Dimond,

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **October 12, 2018**, and initiate remedial activity before **December 11, 2018**. The initial Surface Casing psi was 13. The initial Production Casing psi was 10. The five minute Surface Casing shut in pressure was 12. The production casing pressure followed bradenhead pressure while bradenhead open indicating there is direct communication between bradenhead and production casing.

The gas analysis and wellbore schematic have been received. The gas analysis indicates similar gas on bradenhead and production casing.

Reference: RBDMS MPK1819357449 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File