



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

SEP 17 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-14-18 Operator BP America API #30-0 45-27799
Property Name FEEL: off SWI Well No. 1 Location: Unit D Section 26 Township 30 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 1715 Intermediate 133/8 Casing 95/8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE						FLOW CHARACTERISTICS	
	BH	Bradenhead Int	Csg	INTERM Int	Csg		BRADENHEAD	INTERMEDIATE
TIME								
5 min	0	69	0	0	9	0	2	0
10 min	0	69	0	0	9	0	0	0
15 min	0	69	0	0	9	0	0	0
20 min								
25 min								
30 min								
							Steady Flow	
							Surges	
							Down to Nothing	
							Nothing	
							Gas	
							Gas & Water	
							Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____ 133/8 95/8

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0 0

REMARKS:

BH - Duff when opened 133/8 int - Duff when opened - Duff when opened at 5 min shut-in 95/8 blew 23 seconds - locked - nothing when opened after
By Muhul Witness Mouca (tubing 5 min shut-in)
Well Site Leader
(Position)

E-mail address _____