



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3distric.htm>

NMOCd

OCT 04 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-2-18 Operator Hilltop Energy Co. API #30-0 45-29936
Property Name Oasaly Swd Well No. 2 Location: Unit 22 Section 22 Township 30 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 651 Intermediate 0 Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	-5	0	-5
10 min	0	0	-5	0	-5
15 min	0	0	-5	0	-5
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Puff when opened - Nothing when opened after 5 min shut-in - Int. Nothing when opened - Nothing when opened after 5 min shut-in

By [Signature]

Witness [Signature]

Swd Operators

(Position)

E-mail address _____