OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC , NM 87410
(505) 334-6178 FAX. (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit | copy to above address)

Date of Test	Aug. 18 2018	Operator M&C Dri	lling Company	API#30-0 45-320	08
Property Name			3 Location: Unit C		hip 27N Range 08W
Well Status (Shul-In	n or roducing)	Initial PSI: Tubing	80 Intermediate Nane	Casing 90 Brade	nhead
TESTING TIME 5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	OPEN BRADENHEAI PRESSUE Bradenhead BH INT Csg O 90 O 90 O 90		TE TO ATMOSPHERE INDIV Steady Flow Surges Down to Nothing Nothing Gas Gas & Water		HARACTERISTICS INTERMEDIATE
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS: Start test 2:15 pa - 2:35 pa Bradenhead pared when opened.					
Ву	(Positio		Witness		
E-mail address	(FOSHIO			NMOCD SEP 27	
				DISTRICT	111