



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-18-18 Operator Enduring Resources API #30-045-35564

Property Name Chaco 2308-114 Well No. 4074 Location: Unit A Section 11 Township 23 Range 8

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 73 Intermediate 0 Casing 582 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	—	<u>0</u>	<u>582</u>	—	<u>582</u>
10 min	—	<u>0</u>	<u>582</u>	—	<u>583</u>
15 min	—	<u>0</u>	<u>582</u>	—	<u>583</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing	X		X
Gas			
Gas & Water			
Water			NMOCD

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OCT 18 2018

DISTRICT III

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Nothing on Intermediate when opened - Nothing after five minute shut in.
Nothing on BH when opened - Nothing after five minute shut in -

By Preston Chermans
Engineering Tech
(Position)

Witness [Signature] NMOCD

E-mail address _____