



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

NOV 05 2018

DISTRICT III

(submit 1 copy to above address)

Date of Test 11-2-18 Operator Enduring Res. API #30-0 39-05665
Property Name Jewella B Well No. 22 Location: Unit Section 6 Township 24 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate VIA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE *NA*

REMARKS:

REMARKS: Duff when opened. Nothing when opened
after 5 min shut in

By Jeff Foster

Witness W. Monica Richards

(Position)

E-mail address