

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

OCT 04 2018

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

Farmington Field Office
Bureau of Land Management
5. Lease Serial No. **NM-0468128**
6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		7. If Unit of CA/Agreement, Name and/or No.
2. Name of Operator Hilcorp Energy Company		8. Well Name and No. Hagood 3
3a. Address 382 Road 3100, Aztec, NM 87410	3b. Phone No. (include area code) 505-599-3400	9. API Well No. 30-045-07638
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface Unit P (SESE), 990' FSL & 790' FEL, Sec. 34, T29N, R13W		10. Field and Pool or Exploratory Area Basin Dakota
		11. Country or Parish, State San Juan, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>FAN</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 8/12/1996. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and approved by the Land Owner Tommy Bolack on 4/17/18. Please remove this well from the Hilcorp Energy Company bond.

NMOCB
NOV 01 2018
DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Kandis Roland	Title Operations/Regulatory Technician
Signature <i>Kandis Roland</i>	Date 10/4/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by <i>Sue Ann Swain</i>	Title <i>Supr WRS</i>	Date <i>10/15/18</i>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <i>FRU</i>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Final Reclamation Detail and Approval

Date Well P&A'd: August 12, 1996

Well Name: Hagood 3

Location: Unit Letter P Footages 790' FSL & 790' FEL

Sec. 34; T 29 N, R 13 W; County: San Juan; State: NM

Surface Owner Name: B Square Ranch


Reclamation Detail:

Equipment removed: yes no
(All wellhead surface equipment, tanks, meter runs, piping (removed or capped and abandoned below ground, as appropriate), cathodic equipment, fencing etc.)

Location and road have been re-contoured: yes no

Erosions / Drainage issues addressed with final reclamation: yes no

Location seeded according to Surface Owner request: yes no

I , agree the final reclamation on the subject well has been satisfactorily performed.

(Surface Owner Name): Tommy Bolack

(Address): 3901 Bloomfield Hwy., Farmington, NM 87401

(Date): 4-17-18

Signature: B-Square Ranch - Tommy Bolack

Witness: _____

RCC Reclamation Completion				Location Name: <u>HAGOOD #3</u>			Date: <u>4-17-2018</u>			Revision 2 (3/7/17)								
API#: <u>30-045-07638</u>				UL-Sec-Twn-Rng: " <u>P</u> " <u>T29N R13W Sec 34</u>			Lat/Long: <u>36.6784, -108.18679</u>											
Surface Owner: <u>B SQUARE RANCH</u>				Lease# <u>NM-0468128</u>			County/State: <u>SAN JUAN NEW MEXICO</u>											
Pipeline Owner: <u>ENTERPRISE</u>				Twin/Co-Locate Well Name & Operator:														
Onsite: <u>SAM JAQUER</u>				Agency Inspector:			Contractor:			Seed Mix:								
Interim Reclamation				Completed	Incomplete	N/A	Final Reclamation			Completed	Incomplete	N/A	Remediation			Completed	Incomplete	N/A
Have pit sample results been approved							3rd party pipeline removed				✓		Facilities stripped					
Has water been removed from pit							Anchors removed				✓		Certificate of waste issued & approved					
Have pit marker photos been taken							Equipment and piping removed				✓		Depth:					
Has certificate of waste been issued & approved							Power poles removed						Width:					
Have all pit contents been removed							Cathodic protection removed						Length:					
Has sample after content removal been taken							Vegetative cages removed				✓		Date of Excavation Start:					
Is location contoured							CMP's removed						Date of Excavation End:					
Is there 4' of cover over pit							Non native gravel buried or removed				✓		Date of Backfill Start:					
Has top soil been spread evenly							Noxious weeds removed or sprayed				✓		Date of Backfill End:					
Has all non-native gravel been buried or removed							Invasive weeds removed or sprayed				✓		Yards Hauled Out:					
Has pit liner been removed							Contouring complete				✓		Impacted Soil Hauled To:					
Has all trash been removed							Top soil spread				✓		Yards Hauled In:					
Have all weeds been removed							Diversions clean and functional				✓		Fresh Soil Hauled in From:					
Teardrop allows vehicle access to all facilities							Silt trap clean and functional				✓		Approval to backfill					
Drainage ditches allow adequate run off							Cattle guard / gates removed				✓		Back fill mechanically compacted					
All non-traffic areas disked properly							Cellar / mouse hole covered						Facilities reset					
All non-traffic areas seeded							Erosion under control				✓		Trash and debris removed					
Seeded areas have been mulched							Location properly ripped				✓		Close Out Completed					
Noxious weeds have been removed or sprayed							Location properly disked				✓		Soil Removal Sundry Ready to be Filed					
Invasive weeds have been removed or sprayed							Location seeded				✓							
Barriers set to deter traffic							Photo transect installed											
Silt traps are functional							Access road properly closed				✓							
Culverts are functional							Public use controlled				✓							
Upper diversion is functional							Barriers in place				✓							
Have wellhead cages and jersey barriers been removed							Grazing controlled				✓							
Have reclamation pictures been taken							P&A marker installed & legible				✓							
Growth at least 70%							Well sign removed				✓							
Agency Inspection Date:							Growth at least 70%				✓							
Sundry is ready to file							Trash and debris removed from location				✓							
							Final reclamation photos taken				✓							
							Agency Inspection Date: <u>4-17-2018</u>				✓							
							FAN Ready to be filed				✓							
Comments:							Comments:						Comments:					
							FIELD VISIT WITH											
							Tommy Bolack											