

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of To	est <u>3-28-</u>	06 Operator_	Robert L.	Bayless, producer LLC	API #30- <u>045-32</u>	911
Property 1	Name <u>Floyd</u> V	Well No. 10 Loca	ation: Uni	t J Section 7 Towns	hip 30N Range	12W
Well Stati	us (Shut-In or(	Producing) Tub	ing /50 ]	Intermediate Casir	ng 22 Bradenl	nead_6_
OPEN I	BRADENHEAL	AND INTERME	DIATE TO	ATMOSPHERE INDIV	IDUALLY FOR 15	MINUTES EACH
TIME		PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes_	0		22	Steady Flow		
10 minutes_			22	Surges		
15 minutes_	0		22	_ Down to Nothing	<u> </u>	
20 minutes				Nothing		
25 minutes				Gas		
30 minutes				Gas & Water		
				Water		
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY				SULFURBLACK MAY 2006		
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE INTERMEDIATE						
REMARKS:						
Checked bradenhead, had no pressure						
		· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·	
***************************************						
By B.				Witness		
Pumper (Position)				*** ***********************************		
(	Position)		· · · · · · · · · · · · · · · · · · ·			
E-mail add	ress					