NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-24-18 Operator Maralex API #30-0 45-29797

Property Name Trading Post 22 Well No. 1 Location: Unit ___ Section 22 Township 25N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 4 Intermediate XNA Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		22		
10 min	0		22		
15 min	0		22		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: BH through 1" Fittings, no pressure

By Eric Craw Witness ✓

Mechanic
(Position)

E-mail address _____

NMOCD
DEC 10 2018
DISTRICT III