



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://omnrd.state.nm.us/ocd/District III/3distric.htm](http://omnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-23-18 Operator Maralex API #30-0 45-32944

Property Name Pinar 35 Well No. 44 Location: Unit Section 35 Township 25N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 16 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		16		
10 min	0		16		
15 min	0		16		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE NA

REMARKS: BH through 1" Fittings - no pressure

By [Signature]
Mechanic
(Position)

Witness

E-mail address

10/23/18
10:23
10/23/18 111