



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3dstric.htm](http://emnrd.state.nm.us/ocd/District%20III/3dstric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-24-18 Operator Maralex API #30-0 45-34698

Property Name Trading Post 27 Well No. 2T Location: Unit Section 27 Township 25 Range 11N

Well Status (Shut-In or Producing) Initial PSI: Tubing 68 Intermediate NA Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: BH through 1" Fittings, nothing

By Eric Crow
Mechanic
(Position)

Witness ✓

E-mail address

W3300D
DEC 10 2018
DISTRICT III