Form 3160-5

LINITED STATES

FORM APPROVED

(June 2015)	DE	PARTMENT OF THE I	NTERIOR	DEC	1 / 20		ires: January 31, 2018	
	BUREAU OF LAND MANAGEMENT					5. Lease Serial No. SF-078362		
Do aba	not use this	NOTICES AND REPO form for proposals t Use Form 3160-3 (A	o drill or t	o re-enter an	and Man	6fficindian, Allottee or agement N/A	Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well						N/A		
☐ Oil Well ☐ Gas Well ☐ Other						8. Well Name and No.	Marcus #7	
2. Name of Operator DJR Operating, LLC						9. API Well No. 30-039-24035		
3a. Address 1 Ro	NM 87410		(include area code)		10. Field and Pool or Exploratory Area			
			505-632-347	6		Lybrook Gallup		
	R.,M., or Survey Description)		11. Country or Parish, State Rio Arriba County, New Meixco					
640 FSL, 2005 FWL, N-Sec. 1-T23N, R7W								
	12. CHE	ECK THE APPROPRIATE BO	OX(ES) TO IN	DICATE NATURI	E OF NOTIO	CE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION TYPE OF AC						TION		
Notice of In	tent	Acidize	Deep			uction (Start/Resume)	Water Shut-Off	
_		Alter Casing		raulic Fracturing	✓ Recla		Well Integrity	
✓ Subsequent Report Casing Repair New Construction Record Change Plans Plug and Abandon Temp						orarily Abandon	Other	
						Disposal		
the proposal is the Bond under completion of t	to deepen directions which the work wi he involved operational Abandonment No	ally or recomplete horizontally Il be perfonned or provide the ons. If the operation results in	y, give subsurfa Bond No. on f a multiple con	ace locations and notice with BLM/BIA appletion or recomp	neasured and Required solletion in a n	d true vertical depths of subsequent reports must new interval, a Form 310	k and approximate duration the fall pertinent markers and zone t be filed within 30 days follow 60-4 must be filed once testing e operator has detennined that t	s. Attach ing has been
The Marcus	#7 plugged and al	pandoned on 11-16-2007.						
							ad all surface equipment rem nd facilities within the well pa	
The site has	been re-contoured	d, reseeded and all other sp	pecified requir	rements per the f	Reclamatio	n Plan as approved b	by the BLM-FFO.	
Per Robert S	witzer, BLM-FFO	AO, the site has been foun	d to comply w	vith the interim re	quirements	s under the BLM guid	elines and the Reclamation I	Plan.
Final Reclam	ation/FAN will be	forthcoming as the site me	ets BLM final	reclamation vege	etation star	ndards.		
						NMOC	D	
						DEC 2 1	2018	
)				DISTRICT	111	
,	rue and correct Name (Prin	ited/Typed)	Landman		No. as	-ABY		
Paul Lehrman	X			Title				
Signature				Doto		12/14/201	18	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THE SPACE FOR FEDERAL OR STATE OFICE USE

Title

Office

Accepted for Record

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.



Approved by

DEC 1 7 2018

Date

Attached to Sundry for Interim Reclamation Approval dated 12-14-18.

MARCUS #7

SURFACE:

FEDERAL

MINERALS:

FEDERAL

LEASE NO .:

SF-078362

API#: 3003924035 Well Name: MARCUS # 007

Location: N-1-23.0N-07W, 640 FSL, 2005 FWL Lat:36.2485242854 Long: -107.529589069

Operator Name: ELM RIDGE EXPLORATION COMPANY County: Rio Arriba Land Type: Federal Well Type: Oil Spud Date:9/9/1986 1 Plug Date:11/16/2007

Elevation GL: 7022 Depth TVD: 5790

Pools associated:

LYBROOK GALLUP




Photo Taken 12-13-2018. Interim Reclamation October 2018

Looking North from SW Corner of pad




Photo Taken 12-13-2018. Interim Reclamation October 2018

Looking Northwest from SW corner of pad. Note barrier fence along road other wells in area




Photo Taken 12-13-2018

Looking NE from SW Corner of Pad. Note barrier fence along east edge of road. Pad has main access road cutting it in half




Photo Taken 12-13-2018

Looking East from access road