



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 09/12/2018 Operator Mustang Resources LLC API #30-045-28115

Property Name Susan Com 34 Well No. 01 Location: Unit A Section 34 Township 28N Range 10W

Well Status (~~Shut-In~~ or ~~Producing~~) Initial PSI: Tubing 21.9 Intermediate NA Casing 21.8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>21.7</u>		
10 min	<u>0</u>	<u>NA</u>	<u>21.7</u>		
15 min	<u>0</u>	<u>NA</u>	<u>21.8</u>		
20 min					
25 min					
30 min					
				Steady Flow	
				Surges	
				Down to Nothing	
				Nothing <u>✓</u>	
				Gas	
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

(SI) Compressor was down during Test

Casing PSI > 20% change since last Test 6 psi to 21.8 psi

Bradenhead PSI Remained the same

By [Signature]
Production Foreman
(Position)

Witness _____

E-mail address djohnson@mustangresourcesllc.com

NEW MEXICO
OCT 01 2018
DISTRICT III