



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC

JAN 14 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-14-19 Operator Hilcorp Energy API #30-0 39-277 84
Property Name SS 29.5 UH Well No. 21B Location: Unit 5 Section 08 Township 29 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 95 Intermediate 0 Casing 114 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	115	0	116
10 min	0	-2	115	0	116
15 min	0	0	115	0	117
20 min	0	0	116	0	117
25 min	0	0	116	0	117
30 min	0	0	116	0	117

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Light blow when opened. Nothing when opened after 5 min shut-in. Int - Sulfur when opened. Nothing when opened after 5 min shut-in.

By Kyle D Smith

Witness Monica Luchins

(Position)

E-mail address _____