



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 1-10-19 Operator Hilcorp Energy API # 30-0 45-25146

Property Name State B Gas Com Well # 1E Location: Unit Sec 16 Twn 29 Rge 10

Land Type:

State
Federal
Private
Indian

NMOCD

JAN 10 2019

DISTRICT III

Well Type:

Water Injection
Salt Water Disposal
Gas Injection
Producing Oil/Gas ✓
Pressure observation

Temporarily Abandoned Well (Y/N): 0 TA Expires:

Casing Pres. 0 Tbg. SI Pres. Max. Inj. Pres.
Bradenhead Pres. 0 Tbg. Inj. Pres.
Tubing Pres. ✓/A
Int. Casing Pres. ✓/A

Pressured annulus up to 562 psi. for 30 mins. Test passed/failed

REMARKS:

3710 to surface - Casing repair BH puff when opened.
dropped to 542 from 562 in 30 min - holes were air
3700 -
for recomplete -

By Craig Ward Witness Mona Cuchling
(Operator Representative) (NMOCD)
Consultant
(Position)

Revised 02-11-02