



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

JAN 25 2019

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 1/25/2019 Operator Hilcorp Energy API # 30-0 45-11042

Property Name Dusenberry Well # 3 Location: Unit I Sec 1 Twn 31 Rge 12

Land Type:

State _____
Federal _____
Private X _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. NA Max. Inj. Pres. NA
Casing Head Pres. 0 - open when arrived Tbg. Inj. Pres. NA
Tubing Pres. NA
Int. Casing Pres. NA

Pressured annulus up to 642 psi. for 30 mins. Test passed/failed

REMARKS: Tested from CIBP @ 7355' to surface, squeezed 5760-5761 and 5560-5561. 1000 lbs
spring, 1 hr clock, 1 hr 1000 lbs clmt. Pressured up to 642 psi, 5 min 641 psi BH O psi
10 min 640 psi BH O psi, 15 min 639 psi BH O psi, 20 min 638 psi BH O psi, 25 min
637 psi BH O psi, 30 min 637 psi BH O psi, bled back down to 0 psi

Emmanuel
(Operator Representative)
Well Site Supervisor
(Position)

Witness John D. Kelly
(NMOCD)

Revised 02-11-02