



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC

JAN 25 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-25-19 Operator Hilcorp Energy API #30-0 45-20814
Property Name Huerfano U. #1 Well No. 219 Location: Unit 29 Section 29 Township 26 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 41 Intermediate 1A Casing 80 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		80		
10 min	0		79		
15 min	0		80		
20 min	0		80		
25 min	0		81		
30 min	0		80		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing ✓ _____
Gas _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1A

REMARKS:

Nothing when opened. Nothing when opened
after 5 min shut in

By Chasin

Witness Mona Tuckling

operator
(Position)

6 month test
1 year test

E-mail address _____