



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

NMOCD

JAN 25 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-24-19 Operator H. Cap Energy API #30-0 45-26563

Property Name Lackey 3LS Well No. 12M Location: Unit 21 Section 28 Township 28 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 77 Intermediate 7A Casing 78 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		74		
10 min	0		80		
15 min	0		81		
20 min	0		82		
25 min	0		82		
30 min	0		83		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 7A

REMARKS:

Nothing when opened - Nothing when opened  
after 5 min shut-in  
- this well does not have an intermediate

By Frank Raskid

Witness Monica Cushman

(Position)

Re-test in 1 year

E-mail address \_\_\_\_\_