



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 26 FEB 2019 Operator OR API # 30-0 45-33944

Property Name BISTI WALLUP 20 Well # 2 Location: Unit B Sec 20 Twn 25 Rge 12

and Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Ising Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Casinghead Pres. _____ Tbg. Inj. Pres. _____
Ising Pres. _____
t. Casing Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: 1000 PSI SPRING, 60 MINUTE CLOCK
THE CASING WAS PRESSURED UP TO 585 PSI AND PRESSURE
HELD FOR THE ENTIRE TEST

A BULGEHEAD TEST NEEDS TO BE PERFORMED IN 30 DAYS, 6 MONTHS AND 1 YEAR.

by Jesus F. Carmona
(Operator Representative)

Witness

[Signature]
(NMOCD)

(Position)

NMOCD

Revised 02-11-02

FEB 26 2019

DISTRICT III