



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 26 FEB 2019 Operator DJR API #30-0 45-32944

Property Name BISTIGALLUP Well No. 2 Location: Unit B Section 20 Township 2S Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 585 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>585</u>		
10 min	<u>0</u>		<u>585</u>		
15 min	<u>0</u>		<u>585</u>		
20 min	<u>0</u>		<u>585</u>		
25 min	<u>0</u>		<u>585</u>		
30 min	<u>0</u>		<u>585</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	<u>N/A</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING
CAME OUT

By Jesus F. Carmona

Witness [Signature]

(Position)

E-mail address _____

NMOC

FEB 26 2019

DISTRICT III