



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 1-5-2018 Operator Hilcorp Energy API # 30-045-08766

Property Name Shults Federal Well No. 1 Location: Unit Section 1 Township 29 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 555 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	0	0	555			Steady Flow	
10 min	0	0	545			Surges	
15 min	0	0	540			Down to Nothing	X
20 min						Nothing	
25 min						Gas	X
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Open INTERMEDIATE

REMARKS:

Very light puff to nothing in one second. Nothing on BH after five minute shut in -

BH test during MIT - BH was closed this morning -

By [Signature]
OPERATIONS ENGINEER
(Position)

Witness [Signature] WMOCD

E-mail address SPIVNICKA@HILCORP.COM