



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

NMOCD

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAR 10 2019

DISTRICT III

Date of Test 3/10/2019 Operator Hilcorp API #30-045-23729

Property Name Keys Gas Com D Well No. 1E Location: Unit I Section 29 Township 29 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>581</u>
10 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>580</u>
15 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>579</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	<u>X</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Nothing on BH. Ran Int position during MIT. Casing pressured up to 582 psi at start of Intermediate. Nothing on Int when opened.

By Dana Phillips

Witness Jonah D. Kelly

(Position)

E-mail address _____