



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOC

MAR 21 2010

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3-21-19 Operator Hilcorp Energy Co. API # 30-0 39-24518

Property Name SS306 1st SWD Well # 2 Location: Unit 23 Sec 23 Twn 30 Rge 7

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal /
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N) (N) TA Expires:

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 620
Int. Casing Pres.

Tbg. SI Pres.
Tbg. Inj. Pres.

Max. Inj. Pres.

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS:

Picker set at 7837
top of pay - 7971
dropped to 554-

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOC)

[Signature]
(Position)

Revised 02-11-02