



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3-21-19 Operator Hibon Energy Co API # 30-0 45-09068

Property Name Capine SWD Well # 1 Location: Unit 33 Sec 30 Twn 30 Rge 13

Land Type:

State
Federal
Private
Indian

NMOCD
MAR 21 2019
DISTRICT III

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. 0 Tbg. SI Pres. Max. Inj. Pres. 1100
Bradenhead Pres. 804 Tbg. Inj. Pres.
Tubing Pres. 804
Int. Casing Pres. N/A

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS:

Pucker Det 3996
top puf. 3830

By [Signature] (Operator Representative)
SWD Operator (Position)
Witness [Signature] (NMOCD)

Revised 02-11-02