



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District II/3district.htm](http://emnr.state.nm.us/ocd/District%20II/3district.htm)

NMOC

APR 15 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-12-19 Operator 4 (1) Corp Energy Co API # 30-039-30642
Property Name San Juan 287 Well No. 234 Location: Unit 9 Section 15 Township 28 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 96 Intermediate 0 Casing 99 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	99	0	100
10 min	0	0	99	0	101
15 min	0	0	100	0	101
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH Nothing when opened Nothing when opened after 5 min Shut-in Int Blew to clear at 5 seconds. Nothing when opened after 5 min Shut-in

By Mark E Goodwin

Witness Monica Kuehling

(Position)

E-mail address _____