



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOC

APR 16 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 4-16-19 Operator Dugan Prod. API #30-0 45-35870

Property Name BH Unit SWD 33 Well No. 4 Location: Unit 7 Section 33 Township 24 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 1/1 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

BH blew to dead in 3 seconds - nothing
When opened after 5 min shut in

By Jason Healy

Witness Nemca Fuchling

(Position)

E-mail address _____