



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District III/3distr.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 21-JUNE-2019 Operator DMINION API #30-0 31-20120
Property Name SOUTH HESSAH Well No. 29 Location: Unit B Section 12 Township 17 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Int	Csg	Int	Csg	
TIME	<u>0</u>	<u>N/A</u>	<u>0</u>			
5 min	<u>0</u>	<u>0</u>	<u>0</u>			
10 min	<u>0</u>	<u>0</u>	<u>0</u>			
15 min	<u>0</u>	<u>0</u>	<u>0</u>	<u>N/A</u>		
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By [Signature]
(Position)

Witness [Signature]

E-mail address

NMOC

JUN 21 2019

DISTRICT III