



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 6.13.19 Operator Southland Royalty API # 30-0 39-24454

Property Name Quintana Mesa Well # 100 Location: Unit K Sec 28 Twn 32 Rge 5

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation ☒ _____

NMOCD
JUN 13 2019
DISTRICT III

Temporarily Abandoned Well (Y/N): Y TA Expires: 6.13.2024

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 1245
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 560 psi. for 30 mins. Test passed/failed

REMARKS: BH Casing - tubing
0 560 1245
0 560 1245 packer set 3759
0 560 1245
0 560 1245 dufs 3848-3904
0 560 1245
0 558 1245

By Dan J. [Signature]
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

Lease Operator
(Position)

Revised 02-11-02

60

Southland
Sec 28-32N-05W
30-039-24454

5

55

DISTRICT III
JUN 13-2019
MOC

900
800
700
600
500
400
300
200
100



Graphic Controls

06-13-2019

CHART NO. MC MP-1000-1HR

well been
of far nington

HJL

CHART PUT ON

TAKEN OFF

M

M

LOCATION Quintang Mesa, Co. #100

REMARKS 1 line = 14 hrs
1 line = 20 psz

Remain fueling
MOC
13.19
used

Danys H

30

25

35