



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/1/19 Operator ENDURING RESOURCES IV LLC API # 30-043-21226

Property Name: CHACO 2206 5A Well No: 436H Location: Unit A Section 05 Township 22N Range 06W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 46 Intermediate N/A Casing 46 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	Ø		46			
10 min	Ø		46			
15 min	Ø		46			
20 min	Ø		46			
25 min	Ø		46			
30 min	Ø		46			

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE N/A

REMARKS:

Bradenhead blew down to no flow after approximately 3 seconds.

By John Dockter

Witness _____

HSE Tech
(Position)

E-mail address JDockter@EnduringResources.com

WOOD
MAY 14 2019
DISTRICT III