



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

NMOC

JUN 14 2019

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 6/14/2019 Operator Logos Operating API #30-0 45-06621
Property Name Richardson Well No. 2 Location: Unit P Section 11 Township 27 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 530 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		555		
10 min	0		551		
15 min	0		548		
20 min	0		541		
25 min	0		539		
30 min	0		537		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.1 INTERMEDIATE NA

REMARKS:

BHT ran during MIT. Perform follow up BHT in 30 days, to be witnessed. Light casing pressure loss during test, no flow observed through BH, observed BH with gauge to 55 min on MIT remained @ 0.1 psi. - Follow up BHT schedule 7/12/2019.

By Eugene Burbank
Production Foreman
(Position)

Witness [Signature]

E-mail address _____