



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

NMOC

JUN 07 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-7-19 Operator Hilcorp Energy API #30-0 45 06916
Property Name Martin Creek Well No. 1 Location: Unit 3 Township 27 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 84 Intermediate Casing 101 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		101		
10 min	0		102		
15 min	0		102		
20 min	0		103		
25 min	0		103		
30 min	0		103		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Bradenhead repair. 30 day test. Light puff
when opened. Nothing when opened after 5 min
Shut in

By Billy Pennington
Pumper
(Position)

Witness Monica Kuchling
6 month & 1 year

E-mail address