



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOC

JUN 11 2019

DISTRICT III

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.11.19 Operator Rugart, R API #30-0 45-22295

Property Name Leofrene SWD Well No. 1 Location: Unit Section 17 Township 25 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing 400 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead		INTERM			
	BH	Int		Int	Csg	
TIME						
5 min	<u>0</u>					
10 min	<u>0</u>					
15 min	<u>0</u>					
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing	<u>✓</u>	
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Light blow to dead in 5 seconds. nothing when
opened after 5 min shut in

By Jason H. [Signature]

Witness

(Position)

E-mail address