



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 14-JUNE-2019 Operator HILLARD API # 30-0 45-27956

Property Name KAHDES PAH Well # 2 Location: Unit K Sec 18 Twn 26 Rge S

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: 1000PSI CHART 60 MINUTE CLOCK
THE CASING WAS PRESSURED UP TO 570 PSI AND PRESSURE FELL
TO 540 AND HELD THE LAST 10 MINUTES

By [Signature] (Operator Representative)
Witness [Signature] (NMOCD)
Willie Siquerra
(Position)

NMOCD

Revised 02-11-02

JUN 17 2019