



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR EIC)

Date of Test 6.11.19 Operator Wagon Road API # 30-0 4532086

Property Name Mesa SW Well # 4 Location: Unit 16 Sec 24 Twp 8 Rge 8

Land Type:

State
Federal
Private
Indian

NMOCD
JUN 11 2019
DISTRICT III

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 450
Int. Casing Pres.

Tbg. SI Pres. 450
Tbg. Inj. Pres.

Max. Inj. Pres.

Pressured annulus up to 390 psi. for 30 mins. Test passed/failed

REMARKS:

dropped to 385 & held.

Packer Set 4222


Log Perf. 4288 - 4438

By Samuel
(Operator Representative)

Witness Monica Kuehling
(NMOCD)

(Position)

Revised 02-11-02



NMOCB

JUN 11 2019

DISTRICT III



Graphic Controls

30.045 32086

CHART NO. MC MP-1000-1HR

METER

CHART PUT ON

TAKEN OFF

LOCATION

Mesa SWD #4

REMARKS

16.24.8

Mesa Kullberg
NMOCB
6-11-19
Passel.

James Healey

PRINTED IN U.S.A.