



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-10-14 Operator Hilcorp Energy Co API #30-0 45-32943
Property Name Salty Dog SWB Well No. 6 Location: Unit C Section 19 Township 29 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 713 Intermediate 1/A Casing 2 Bradenhead 31

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		-10		
10 min	0		-10		
15 min	0		-10		
20 min	0		-10		
25 min	0		-10		
30 min	0		-10		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/A

REMARKS:

Blew to light flow in 15 seconds. Light flow for rest of 30 min. Test - requested gas analysis from bradenhead - Had blow when opened after 5 min shut in

By [Signature]

Witness [Signature]

(Position)

E-mail address _____