



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOCB

JUN 27 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

http://emnr.state.nm.us/ocd/District/III/3distric.htm

Date of Test 6-27-19 Operator Hilco Energy API #30-0 45-34408
Property Name Allison Unit Well No. 61W Location: Unit 7 Section 7 Township 32 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 144 Intermediate 398 Casing 144 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg	BRADENHEAD	INTERMEDIATE
5 min	0	398	146	80	80/47	Steady Flow	<u>✓</u> Vapors <u>-</u>
10 min	0	398	146	1	148	Surges	
15 min	0	398	147	0	148	Down to Nothing	
20 min				0	148	Nothing	<u>✓</u>
25 min				0	148	Gas	<u>✓</u>
30 min				0	149	Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Tat has not been blown down BH Nothing
When opened Nothing when opened after 5 min
Shut in Int. had blow when opened - Surging at 2.5 min
all the way open at 4 min
light blow at
13 min - light at
20 - light at 25
Vapors at 30 min
Dennis W. I. Chalk
blow up in 24 hours
Puff when opened after 5-min
Shut in

By [Signature]

Witness [Signature]

(Position)

E-mail address