



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

NMOCd

JUN 18 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-17-19 Operator Hil Corp Energy API #30-0 45 35263
Property Name Gienier B Well No. 32 Location: Unit 0 Section 5 Township 29 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 102 Intermediate 17 Casing 101 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	17	102		
10 min	0	17	102		
15 min	0	17	102		
20 min					
25 min					
30 min					

unable to test

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____
Surges _____
Down to Nothing ☒
Nothing _____
Gas ☒
Gas & Water _____
Water _____

unable to test

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

BH puff when opened - nothing when opened after 5 min shut in - Int - had liquid - no wave to measure - stopped test.

By Nate Nichols

(Position)

Witness

Monica Cuckling
Catch sample of intermediate
Retest in 30 days.

E-mail address _____