



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOCd

JUN 21 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.21.19 Operator Hilco Energy API # 30-045-35263
Property Name Grenier B Well No. 37 Location: Unit 0 Section 5 Township 29 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 94 Intermediate 1 Casing 96 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	98	0	101
10 min	0	1	100	0	102
15 min	0	1	100	0	102
20 min				0	103
25 min				0	103
30 min				0	104

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH long puff when opened - nothing when opened after 5 min shut-in. Int. long puff when opened. Nothing after 5 min shut-in

By Nate Nichols
(Position)

Witness Mona Kuehling
Retest one year

E-mail address _____