



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distrct.htm](http://emnrd.state.nm.us/ocd/District%20III/3distrct.htm)

NMOC

JUN 18 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.17.19 Operator Hilcorp Energy Co API #30-0 45-35416

Property Name Houck Com Well No. 2N Location: Unit 7 Section 7 Township 29 Range 10

Well Status(Shut-In or Producing) Initial PSI: Tubing 120 Intermediate 5 Casing 124 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	5	126	0	130
10 min	0	5	127	0	131
15 min	0	5	128	0	131
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas	/	/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH- long puff to head at 2 seconds. Nothing when opened after 5 min shut in. Int- long puff to head at 3 seconds. Puff when opened after 5 min shut in.

By Nate Nichols

Witness Monica Tucker

(Position)

E-mail address _____