



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

DISTRICT III

JUL 01 2019

MOON

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.28.19 Operator Hilcorp Energy API #30-0 39-20291
Property Name Scurilla 101 Well No. 2 Location: Unit 12 Section 12 Township 26 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 182 Intermediate 174 Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		200		
10 min	0		201		
15 min	0		201		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD INTERMEDIATE	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	✓	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 174

REMARKS:

Nothing when opened - Nothing when
opened after 5 min shut in

By [Signature]

(Position)

Witness [Signature]
[Signature]

E-mail address _____