



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3distric.htm](http://emnr.state.nm.us/ocd/District%20III3distric.htm)

NMOCd

JUL 01 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6.28.19 Operator Hil Corp Energy API #30-0 39-23467
Property Name AXI Apache N Well No. 7A Location: Unit 13 Section 13 Township 25 Range 4
Well Status (Shut-In or Producing) Initial PSI: Tubing 116 Intermediate 116 Casing 120 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME	0		121		
5 min	0		121		
10 min	0		122		
15 min	0				
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

Nothing when opened. Nothing when
opened after 5 min shut-in

By Julio J

(Position)

Witness

Monica Tuckling
Luanne Huns gic BLM

E-mail address _____