NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

NMOCD
JUN 20 2019
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/18/19 Operator ENDURING RESOURCES IV LLC API #30-039-26628

Property Name RINCON UNIT Well No. 181M Location: Unit F Section 22 Township 27N Range 06W

Well Status(Shut-In or Producing) Initial PSI: Tubing 34 Intermediate 1 Casing 62 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	Ø	1	62	Ø	63
10 min	Ø	1	62	Ø	63
15 min	Ø	1	62	Ø	64
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE Ø

REMARKS: - bradenhead down to nothing in approximatly three seconds
- intermediate blew down to nothing in approximatly fifteen seconds

By John Dockter Witness

HSE Tech
(Position)

E-mail address JDockter@EnduringResources.com

6/19/19