



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOCOD

JUL 11 2019

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

Date of Test 7-10-19 Operator Enduring Res. API #30-0 39-22832
Property Name FinCon Unit Well No. 234 Location: Unit 2 Section 2 Township 26 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 55 Intermediate Casing 63 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		60		
10 min	0		58		
15 min	0		56		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow
Surges
Down to Nothing
Nothing ✓
Gas
Gas & Water
Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE V/A

REMARKS:

Nothing when opened. Started producing
at 3 minutes - Nothing when opened after
5 min shut in

By John Dockter

Witness Monica Kuehling

H3K Tech
(Position)

E-mail address JDockter@EnduringResources.com