



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2 JULY 2019 Operator HILCAP API #30-0 45-35566

Property Name FLORANCE Well No 2M Location: Unit P Section 21 Township 30 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 93 Intermediate 0 Casing 96 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	97	0	97
10 min	0	0	97	0	98
15 min	0	0	97	0	98
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: OPENED THE BRADENHEAD AND PUTTED TO NOTHING.
OPENED THE INTERMEDIATE AND NOTHING CAME OUT.

By Tyler Anderson

Witness John Durham

(Position)

E-mail address _____

NMOCB

III 02 2019

DISTRICT III